BMP C152: Sawcutting and Surfacing Pollution Prevention

PurposeSawcutting and surfacing operations generate slurry and process water
that contains fine particles and high pH (concrete cutting), both of which
can violate the water quality standards in the receiving water. Concrete
spillage or concrete discharge to surface waters of the State is prohibited.
Use this BMP to minimize and eliminate process water and slurry created
through sawcutting or surfacing from entering waters of the State.

- *Conditions of Use* Utilize these management practices anytime sawcutting or surfacing operations take place. Sawcutting and surfacing operations include, but are not limited to, the following:
 - Sawing
 - Coring
 - Grinding
 - Roughening
 - Hydro-demolition
 - Bridge and road surfacing
 - Vacuum slurry and cuttings during cutting and surfacing operations.

Design and Installation Specifications

- Slurry and cuttings shall not remain on permanent concrete or asphalt pavement overnight.
- Slurry and cuttings shall not drain to any natural or constructed drainage conveyance including stormwater systems. This may require temporarily blocking catch basins.
- Dispose of collected slurry and cuttings in a manner that does not violate ground water or surface water quality standards.
- Do not allow process water generated during hydro-demolition, surface roughening or similar operations to drain to any natural or constructed drainage conveyance including stormwater systems. Dispose process water in a manner that does not violate ground water or surface water quality standards.
- Handle and dispose cleaning waste material and demolition debris in a manner that does not cause contamination of water. Dispose of sweeping material from a pick-up sweeper at an appropriate disposal site.

MaintenanceContinually monitor operations to determine whether slurry, cuttings, orStandardsprocess water could enter waters of the state. If inspections show that a
violation of water quality standards could occur, stop operations and
immediately implement preventive measures such as berms, barriers,
secondary containment, and vacuum trucks.